

TÜV INTERCERT S.r.l. - Group of TÜV Saarland

Report no.: RC-0919-SIL-TIC-PC-0010061-17-04

### **SIL SUMMARY REPORT**

IEC 61508-1/7:2010

## Pneumatic / hydraulic compact scotch-yoke double acting actuators

**Series RC** 

Rotork Sweden AB Kontrollvägen, 15 SE-791 22 Falun

Date: 2019-09-12 Place: Reggio Emilia

Author Carlo Tarantola

Signature

This document is only valid in its entirety, without any change.



#### 1 INTRODUCTION

This report summarises the results of the assessment according to standards:

IEC 61508-1/7:2010

for the following products:

pneumatic / hydraulic compact scotch-yoke double acting actuators series RC

#### NOTES:

 The results of this report can be used for the assessment of a complete Safety Instrumented System.

#### 2 ASSESSMENT AND RESULTS

Product identification			
Device	Pneumatic / hydraulic compact scotch-yoke double acting actuators		
Series	RC		
Models / configurations	RC - No on-line monitoring RC - With on-line monitoring RC88 - No on-line monitoring RC88 - With on-line monitoring		
Safety function(s)			
1.	Delivery of a full stroke (90° ± tolerance) driven by the piston of cylinder, powered by the specified medium working pressure.  NOTE: considering the functioning of the actuator to perform the safety function(s), the safety functions "close" and "open" can be considered equivalent.		
Mode of operation of the safety function(s)	High demand mode		
Reference standards			
General functional safety standard	IEC 61508-1/7:2010		
Product specific functional safety standard	None		
Assessment phases			
Management of functional safety / functional safety planning	Assessed	A functional safety audit of the management systems and of the functional safety planning is conducted to document and highlight that the development of the product under consideration is compliant with IEC 61508.	
Safety requirements specification	Assessed	The Safety requirements specification is assessed with respect to its consistency and completeness in a comparison with the applicable requirements of IEC 61508.	

TÜV INTERCERT S.r.I. – Group of TÜV Saarland Report no.: RC-0919-SIL-TIC-PC-0010061-17-04

Via Cecati 1/1 Rev.: (

I-42123 Reggio Emilia

e-mail: info@tuvintercert.it

Job no.: TIC-PC-0010061-17-0044-19
Order no: Rotork order dated 2019-06-21



Design	Assessed	<ul> <li>The assessment of the design included the following aspects:</li> <li>Quantifiable aspects: random failure rates, DC, SFF, PFH, β factors, MRT, PTC, architectural constraints</li> <li>Non-quantifiable aspects: behaviour of the safety function under fault conditions, safety-related software (not applicable to the product under consideration), systematic failures, behaviour under environmental conditions</li> <li>See below for the results.</li> </ul>		
Verification and Validation	Assessed	The verification and validation activities performed by the manufacturer include review, analysis and tests.		
Information for use	Assessed	<ul> <li>The assessment covers:</li> <li>the installation, operation and maintenance instructions (IOM Manual)</li> <li>the particular instructions required by Annex D of IEC 61508 Part 2 (Safety Manual)</li> </ul>		
Modification	Assessed	Procedures for modification activity are described in specific documents, referenced in the safety planning.		
Results				
Selected assessment routes	<ul> <li>For architectural constraints: Routes 1<sub>H</sub> and 2<sub>H</sub></li> <li>For Systematic Capability: Route 1<sub>S</sub></li> <li>Furthermore, the requirements in paragraphs 7.4.10.1–7.4.10.7 of IEC 61508 Part 2 are assessed and considering fulfilled, as:         <ul> <li>the product has a restricted and specified functionality and is designed to perform specified safety functions</li> <li>the product has an adequate documentary evidence (including extensive operating experience and results of suitability analysis and testing), sufficient to claim the declared failure rates</li> <li>the manufacturer has an effective system for reporting failures</li> </ul> </li> </ul>			
Element type (A or B)	Type A			
HFT	The product has a single channel configuration, HFT=0.			

Via Cecati 1/1 I-42123 Reggio Emilia e-mail: info@tuvintercert.it

Rev.: Job no.: TIC-PC-0010061-17-0044-19 Order no: Rotork order dated 2019-06-21



Random failure rates	The determination of random failure rates is performed with a FMEDA, integrated with field feedback, according to IEC 61508 Part 2 Par. 7.4.4.3.3, using the Bayesian approach.			
Configuration	Safety function	λ <sub>DU</sub> [1/h]	λ <sub>DD</sub> [1/h]	λ <sub>s</sub> [1/h]
RC - No on-line monitoring	1	1,45E-08	0,00E+00	0,00E+00
RC - With on-line monitoring	1	1,30E-09	1,32E-08	0,00E+00
RC88 - No on-line monitoring	1	2,62E-08	0,00E+00	0,00E+00
RC88 - With on-line monitoring	1	2,36E-09	2,39E-08	0,00E+00
Spurious trip rate		of components of The "spurious trip		
DC	Diagnostic is on monitoring by the On-line monitoring the actual the Safe Demand Utilization	ing by the proce ator has a very h ty Function oper I Rate at leas on Rate of the actor the external c	xternal means, eas is considered High Utilization F ates in LDM, or i t ten times lo	e.g. with on-line relevant if: Rate n HDM but with ower than the
SFF	<ul> <li>Considering that λ<sub>S</sub>=0, according to definitions 3.6.15 of IEC 61508 Part 4:</li> <li>SFF=0 without external diagnostic tests</li> <li>SFF&gt;0 with external diagnostic tests, carried out according to definition 3.8.7 of IEC 61508 Part 4, and according to what written in the Safety Manual</li> </ul>			
PFH	<ul><li>RC - No on-</li><li>RC - With or</li><li>RC88 - No or</li></ul>	line monitoring: n-line monitoring n-line monitorin n on-line monitor	1,45E-08 [1/h] j: 1,30E-09 [1/h] g: 2,62E-08 [1/h	]
β factors	values for of to IEC 6150  • The above valued redundancy	value is the value ther architecture 8 Part 6, Table I value is calculate without diversity an be used wher tectures.	s shall be calcul 0.5. ed in the hypothe v	ated according
MRT	24 h The MRT considered is the Technical Mean Repair Time, i.e., it takes in consideration availability of skilled personnel, adequate tools and spare parts.			
PTC		for the Proof Tes		the Safety

Via Cecati 1/1 I-42123 Reggio Emilia e-mail: info@tuvintercert.it

Rev.: Job no.: TIC-PC-0010061-17-0044-19 Order no: Rotork order dated 2019-06-21



Architectural constraints	<ul> <li>The product can be used in:</li> <li>single channel configuration:         <ul> <li>up to SIL 2 without external diagnostic tests</li> <li>up to SIL 3 considering external diagnostic tests</li> </ul> </li> <li>double channel configuration: up to SIL 3</li> </ul>
Expected lifetime	25 years
Behaviour of the safety function under fault conditions	The product does not include internal diagnostics.
Safety related SW	No SW is used to implement the safety function.
Systematic Capability	3
Behaviour under environmental conditions Limitations for use	The behaviour in environmental conditions is assessed evaluating the relevant environmental tests.  Make reference to the Safety Manual.

#### Remarks

- The random failure rates in the above table are valid for all the possible configurations of the product.
- According to the definition of IEC 61508 (in particular definitions 3.6.8 and 3.6.13 of IEC 61508 Part 4), no Safe Failures are possible in a double acting actuator: each failure mode of the actuator itself shall be classified as "Dangerous" or "No Effect" (failures which can generate the spurious operation of the safety function are only external to the actuator itself, and even in the case of loss of power supply the actuator "stays put"); hence, λ<sub>S</sub>=0 for each type of double acting actuator.
- Failures of components of the cylinder cannot generate spurious trips.
   The "spurious trip rate" is therefore 0,00E+00 [1/h]
- The  $\lambda_S$  values are not divided in  $\lambda_{SD}$  and  $\lambda_{SU}$ , as this subdivision has no relevance for any of the SIL parameters.
- For further details, make reference to the Safety Manual.

# Reference documents SIL Assessment Report TÜV INTERCERT document no. RC-0919-SIL-TIC-PC-0010061-17-03 Safety Manual Rotork document no. SM-RC-A-00-E

#### 3 STATUS OF THE DOCUMENT

History: R 00: Initial release Date: 2019-09-12

Release status: Released to client Author(s): Carlo Tarantola

TÜV INTERCERT S.r.I. – Group of TÜV Saarland Report no.: RC-0919-SIL-TIC-PC-0010061-17-04

Via Cecati 1/1 Rev.:

I-42123 Reggio Emilia Job no.: TIC-PC-0010061-17-0044-19 e-mail: info@tuvintercert.it Order no: Rotork order dated 2019-06-21

Page 5 of 6



#### **ANNEX A - ABBREVIATIONS AND DEFINITIONS**

Term	Meaning
β, β <sub>D</sub>	Beta common cause factor
λвв	"Black Box" Failure rate – Literature data
$\lambda_{D}$	Failure rate of dangerous failures
$\lambda_{DD}$	Failure rate of detected dangerous failures
$\lambda_{DU}$	Failure rate of undetected dangerous failures
λ <sub>NE</sub>	Failure rate of no effect failures
$\lambda_{S}$	Failure rate of safe failures
λss	"Steady State" Failure rate – Final Value
DC	Diagnostic coverage
FMEDA	Failure modes, effects and diagnostic analysis
HFT	Hardware fault tolerance
High demand mode	Mode, where the frequency of demands for operation made on a safety- related system is greater than one per year
Low demand mode	Mode, where the frequency of demands for operation made on a safety- related system is no greater than one per year
MRT	Mean repair time
PFD	Probability of failure on demand
PFD <sub>AVG</sub>	Average probability of failure on demand
PFH	Probability of failure per hour
PST	Partial stroke test
PTC	Proof test coverage
SFF	Safe failure fraction
SIF	Safety instrumented function
SIL	Safety integrity level
SIS	Safety instrumented system
SLC	Safety lifecycle
SRS	Safety requirements specification
TI	Test interval for proof test (full stroke)
TI <sub>D</sub> (TI <sub>PS</sub> )	Test interval for diagnostic test (partial stroke)
Туре А	"Non-complex" element (using only discrete components to implement the safety function)
Туре В	"Complex" element (using also micro controllers or programmable logic to implement the safety function)

For definitions, standard IEC 61508 (in particular Part 4) applies.

TÜV INTERCERT S.r.l. – Group of TÜV Saarland

Via Cecati 1/1

I-42123 Reggio Emilia e-mail: info@tuvintercert.it Report no.: RC-0919-SIL-TIC-PC-0010061-17-04

Rev.: 00

Job no.: TIC-PC-0010061-17-0044-19 Order no: Rotork order dated 2019-06-21

Page 6 of 6